

# Federal Energy Act Report

October 1, 2012 thru September 30, 2013

(Public Record Posted Date: November 7, 2012)

## General Information:

Total Number of Active UST Facilities: **7,150**  
Total Number of Active/Inactive USTs: **20,334**

## Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **3,587**  
Percent of UST Facilities in SOC Compliance: **63**

## Summary Information For Releases:

Number of Confirmed UST Releases: **316**

## Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	124	39.2	0	0	3	0.9	8	2.5	113	35.8	0	0	0	0	0	0
Piping	17	5.4	0	0	0	0	4	1.2	6	1.9	0	0	0	0	7	2.2
Dispenser	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Submersible (STP)	3	0.9	0	0	0	0	0	0	3	0.9	0	0	0	0	0	0
Delivery Problem	1	0.3	0	0	1	0.3	0	0	0	0	0	0	0	0	0	0
Unknown	171	54.1	0	0	0	0	0	0	0	0	0	0	0	0	171	54.1
Other	1	0.3	0	0	0	0	0	0	0	0	0	0	0	0	1	0.3
Totals	317	100.3	0	0	4	1.3	12	3.8	122	38.6	0	0	0	0	179	56.6

(source of data: Illinois Environmental Protection Agency)

To view site specific information at the Office of the State Fire Marshal, please visit: <http://webapps.sfm.illinois.gov/ustsearch/>

To view the LUST Incident Tracking Database, please visit: <http://epadata.epa.state.il.us/land/ust/Search.asp>